Page 1 of 2

Refer to 1-A01-PPG-001 for Processing Instructions.  Print or Type All Information (Except Signatures)			1. Date 5/6/94		DMR No	94-DMI	R-000999	4 %				
2. Existing Document Number/Revision			3. New Docu	ment Number			be changed with					
		T.6/Rev.2					Revision N/A					
4. Originator's Name/Phone/Page/Location D. Yashan/3692/D1388/7893A			5. Document									
ļ			/3A	1		<b>T</b> (0) i i		Wells and	Piezometer Ins	tallation		
6. Document Type ■ Procedure  7. Document Modification Type (Check only  □ Other □ New □ Revision ■ Intent Char				Change 🗆 1	Editorial Corr	ection 🗆 (	Cancellation					
8. Item	8. Item 9. Page 10. Step						11. Proposed Mod	ifications			<del></del>	
			LIMITEDS	SCOPE: Thi	is DMR is	limited to the I	Dam Upgrades Proje	ect.				
1	3B of 18	Section 6.0	To the first sentence after "and open-pipe piezometers (observation wells)", add the following: ", other types of piezometers, and inclinometers".									
2	4-5 of 18	Section 8.1 P. C. A.										
3	5 of 18	Section 8.22 6 6 20 au			ntaminatio		ownhole equipment tion of work in a wo		ontaminated in	accordance	with SOP FO.	4,
4	9A of	Section	Add Section	3.3.1.6, Incl	linometer		ws: "Inclinometer					
	18	\$.3.1.6					uired by the FSP or					
		6 RR AN		- •		_	irface. The bottom will be fitted with a		•	-	•	
		91,	in the casing	g string will b	e glued ar	d riveted and c	overed with duct tap	pe in order	to support low	er sections o	of casing during	g
							Orientation of the incometer probes, i.e.					
							are perpendicular to					XI.
_				L RP 12494				-				
5	9A of 18	Section \$.3.1.7	Add Section	3.3.1.7, Ce	ment Grou	it, as follows: ace The grout	"The annular space will consist of Port	between the	e casing and bo	rehole will de reduced r	be grouted from H bentonite or	n the
	``	<b>1</b>	mixed in a p	owered mech	hanical mix	er. The grout	will be proportione	d so that its	strength is app	roximately	the same as the	е .
		5/20/94					of the inclinometer					
,		bottom of the casing or with a grout cap/plug assembly that allows for pumping of grout through the inclinometer approximately 2 feet below ground surface."										
			fication, EJO#,				10D	4 949				
installat		illons, and	refections are f	iccessary to p	provide rei	evance of this s	SOP to geotechnical	arming, pie	ezometer instai	iation, and i	ncunometer	
If modifice	tion is for a	new procedure	or a revision, list or	oncurring disciplin	nes in Block 13	, and enter N/A in B	locks 14 and 15. If modifier	ation is for any t	ype of change or a c	ancellation, orga	anizations are listed is	n Block 13,
then Concu	rror prints,	and signs in Blo	ck 14, and dates in	Block 15.	·		· · · · · · · · · · · · · · · · · · ·					
SME		Rob Smith	A La	16d=	Hor		· .				15. Date (if applicat	4
EQS		Mark Brooks	(RR) 1/16		4 191						5.24-94	,
			- 11.1388									
			· · · · · · · · · · · · · · · · · · ·									
16. Origina	tor's Super	risor (print/sign/c	late)									
S. Marsh	all	posi	oun fer	J. A. M.	rossh	rel						
17. Assigned SME/Phone/Page/Location 18. Cost Center Rob Smith/8705/5135/080-643 22.02			19. Charge Num ENV-GT	nber	20. Requested Co 5/23/94	mpletion Date	21. Effecting Date  (0 - 4 - 9)	4 Ime				
	rated Review	v?	23. ORC Review				<b>_</b>			<u> </u>	7 20	<del>'</del>
	No Manag	per (print, sign, d		Not Required; T	This Noninte	nt Change is being	processed as an Intent	t Change to ex	cpedite the DMR	process.		
Steve Sin		t-callen	.,,	ingel	A	Celle V	a hus	3	124/94	,		
		1		<del></del>	0	7	$\mathcal{U}$				LASSIFICATIO	)N/UCNI
			וחחרוי	MENT CLA	SSIFICA	TION REVIEW	V WAIVER	BY DAT				
			PFR (	R.B. HOFFI	MAN. CL	ASSIFICATIO	N OFFICE	DAII				
			1 511	,	HINF 11	1991	- <del>-</del>		ys. a			

ADMIN RECORD

A-SW-002334

Refer to 1-A01-PPG-001 for Processing Instructions.

Print or Type All Information (Except Signatures)

25. DMR. No. 94-DMR- 000994

le los sport			Sizoff(	DMR. No. 94-DMR- 000494			3/3
2. or 3. Document Number/Revision 5-21000-OPS, GT, 2 Rev. 2				3. Document Title Monitoring Wells and Piezometer Installation			
8. Item	9. Page	10. Step	11.	Proposed Modifications			
6	15D of 18	Section 6.3.2.4	Add Section 6.3.2.4, Inclinometer Features, as follows: dimensions will be installed over the inclinometer casing possibility of damage to the casing. The protective casing of the casing will be embedded 2 to 3 feet below the grout the protective casing will be filled with concrete to a mini hole will be drilled in the protective casing just above the At the same time the protective steel casing is concreted in placed around the protective casing at the ground surface. If the concrete to prohibit water from entering the post."	at such a time as to maxing will have the inclinometrial surface in concrete. I mum of 12 inches above concrete surface to allow a place, an external concrete collar will be graded in it before the concrete installed radially for concrete and embedded	nize total productivity and ner designation welded on the free annulus between the incepthe ground surface, and a layer for drainage.  The collar approximately 3 find to slope away from the concrete sets. If traffic or vege from the inclinometer casing in concrete 3 feet below gr	ninimize the e side. The bott linometer casing /4-inch diameter foot square will tasing in all etation conditions g at a distance of round surface wife	tom g and the
7	16-17 of 18	Section 7.0	Change first three sentences of the 2nd paragraph to read documented on appropriate report forms. As a minimum forms."				

12. Justification (Reason for Modification, EJO#, TP#, etc.)

All changes, additions, and deletions are necessary to provide relevance of this SOP to geotechnical drilling, piezometer installation, and inclinometer installation.

EG&G ROCKY FLAT	IS PLANT	Manual: 5-210			
<b>EMD MANUAL OPE</b>	RATION SOP	Procedure No.:	GT.6, Rev. 2		
		Page:	1A of 18		
		Effective Date:	06/01/94		
Category 2		Organization:	Environmental Management		
LIST OF FIGURES					
FIGURE GT.6-1	SCHEMATIC I	DIAGRAM OF ALLUVIAI	. MONITORING		
	WELL COMPL	ETION			
FIGURE GT.6-2	SCHEMATIC I	DIAGRAM OF BEDROCK	MONITORING		
	WELL COMPL	ETION			
		DIAGRAM OF WELL FEATURES AT			
	CDOLDID GUE	PACE			
	THROUND SUB				

## LIST OF EFFECTIVE PAGES

<u>Pages</u>	Effective Date	Change Number
1-5	06/01/94	94-DMR-000801
3B-5	06/01/94	94-DMR-000994
7-18	06/01/94	94-DMR-000801
7	05/11/93	DCN 93.09
9	09/23/93	DCN 93.06
9 <b>A</b>	06/01/94	94-DMR-000994
10	03/17/93	DCN 93.07
13	02/10/93	DCN 93.04
15	02/10/93	DCN 93.04
15	02/10/93	DCN 93.05
15	09/02/93	DCN 93.12
15A	10/01/93	DCN 93.14
15 <b>B</b>	09/02/93	DCN 93.12
15C	10/01/93	DCN 93.14
15C	09/02/93	DCN 93.12
15C	02/10/93	DCN 93.05
15D-16	01/29/93	DCN 93.02
15D-17	06/01/94	94-DMR-000994
Form GT.6A	06/01/94	94-DMR-000801
Form GT.6B	06/01/94	94-DMR-000801

TOTAL NUMBER OF PAGES: 28 (including forms)

EG&G ROCKY FLATS PLANT	Manual:	5-21000-OPS
EMD MANUAL OPERATION SOP	Procedure No.:	GT.6, Rev. 2
	Page:	3B of 18
	Effective Date:	06/01/94
Category 2	Organization:	<b>Environmental Management</b>

- 5.1.3 Submit WIN form and apply for Soil Disturbance Permit fo RFP Construction Management.
- 5.1.4 Receive approved Soil Disturbance Permit.
- 5.1.5 Receive notice from Geosciences Division that well permits have been approved by Division of Water Resources and well installation may proceed.
- 6.0 EQUIPMENT AND PROCEDURES FOR MONITORING WELL AND PIEZOMETER INSTALLATION

Groundwater monitoring wells and open-pipe piezometers (observation wells), other types of piezometers, and inclinometers will be constructed in boreholes drilled and logged according to SOP GT.2, Drilling and Sampling Using Hollow-Stem Auger Techniques, or SOP GT.4, Rotary Drilling and Rock Coring, and SOP GT.1, Logging Alluvial and Bedrock Material. The construction of monitoring wells is the same as that used for piezometers. The distinction between wells and piezometers is based on the intended use. Wells are used for obtaining samples of groundwater while piezometers are intended only for water level measurements. If different types of piezometers are required (e.g., isolated electronic or pneumatic piezometers), they will be addressed in another | SOP or in a project-specific work plan. All drilling

EG&G ROCKY FLATS PLANT	Manual:	5-21000-OPS
EMD MANUAL OPERATION SOP	Procedure No.:	GT.6, Rev. 2
	Page:	4 of 18
	Effective Date:	06/01/94
Category 2	Organization:	Environmental Management

and sampling equipment and materials will be protected from the ground surface with clear plastic sheeting or will be placed on clean drill racks.

Personnel installing monitoring wells need to be cognizant of the many factors influencing the screened intervals selected for wells. For example, water table wells should have screens of sufficient length at the appropriate depth to monitor the water table. Wells with slow recharge should have sufficient screen area to allow adequate sample volume. However, long screened intervals should generally be avoided since they are of limited value for characterizing discrete zones of contamination.

Selection of well screen intervals may also depend on the suspected presence of light or dense immiscible layers of contaminants floating on the water table or residing at the bottom of a hydrostratigraphic unit (HSU). Screened intervals across different HSUs should generally be avoided particularly where there is a potential for cross-contamination between HSUs to occur.

These factors must be addressed during project planning, and the Field Sampling Plan (FSP) will normally provide rationale for the planned sampling. Personnel installing monitoring wells should be familiar with the FSP and the rationale used in determining well screen intervals.

## 6.1 EQUIPMENT AND MATERIALS

The following is a list of equipment and well materials for well installation:

•	Drill rig with appropriately-sized drill bits, augers, and/or rod
•	High pressure steamer/sprayer
•	Sand bailer
•	Long-handled bristle brushes
•	-Wash/rinse-tubs

Manual:

5-21000-OPS

GT.6, Rev. 2

5 of 18 06/01/94

**EMD MANUAL OPERATION SOP** Procedure No.: Page: **Effective Date:** Category 2 Organization: **Environmental Management** 44-DMR-000994 Phosphate free, lab grade detergent (e.g., Liquinox) Weighted tape measure Water level probe

- Drums for containment of cuttings, if necessary
- Appropriate health and safety equipment

Distilled-RFP potable water

- Field book
- Location map
- Boring log form
- Groundwater observation well report

#### 6.2 **DRILLING PROCEDURES**

EG&G ROCKY FLATS PLANT

Boreholes for wells will be drilled by using a drill rig and drilling method capable of completing the well to the depth specified in the FSP. All drilling equipment, including the drill rig, water tanks, and all downhole equipment will be decontaminated according to SOP FO.3, General Equipment Decontamination and SOP FO.4, Heavy Equipment Decontamination. Downhole equipment will be decontaminated between boreholes, and other equipment such as the drill-rig will be decontaminated between different work areas in accordance with SOP FO.4 (Heavy Equipment Decontamination upon completion of work in a work area.

Before drilling, test borings/wells will have been located, numbered, and identified by using stakes or paint sticks on paved surfaces. Drilling locations will be cleared for buried metal objects and utility interference according to SOP GT.10, Borehole Clearing. Boreholes will be advanced from the ground surface to a predetermined target depth given in the FSP. Boreholes drilled for wells will be logged stratigraphically by examination of the sample cuttings or core samples according to SOP GT.1, Logging Alluvial and Bedrock Material.

94-DmR-000801

44-DMR-000994

EG&G ROCKY FLATS PLANT EMD MANUAL OPERATION SOP

Manual: Procedure No.: 5-21000-OPS

Page:

GT.6, Rev. 2 9A of 18

Category 2 Effective Date: Organization:

06/01/94 Environmental Management

## 6.3.1.6 Inclinometer Casing

Inclinometer casing will consist of new, flush-joint acrylonitriles butadiene styrene (ABS) unless another type of casing is required by the FSP or project-specific workplan. The inclinometer casing will extend to approximately 2 feet above the ground surface. The bottom of the casing will be fitted with a slip-in cap that will be glued and riveted in place. The top of the casing will be fitted with a slip-in cap which can be easily removed by hand. All joints in the casing string will be glued and riveted and covered with duct tape in order to support lower sections of casing during installation and to prevent inflow of cement grout. Orientation of the inclinometer casing will be such that the grooves inside the casing will allow for proper placement of the inclinometer probes, i.e., one set of two grooves are parallel to the anticipated direction of movement and one set of two grooves are perpendicular to the anticipated direction of movement.

#### 6.3.1.7 Cement Grout

The annular space between the casing and borehole will be grouted from the bottom of the casing to ground surface. The grout will consist of Portland cement and high-solids reduced pH bentonite grout mixed in a powered mechanical mixer. The grout will be proportioned so that its strength is approximately the same as the surrounding material. Grout will be placed outside of the inclinometer casing using a side discharge tremie pipe located at the bottom of the casing or with a grout cap/plug assembly that allows for pumping of grout through the inclinometer approximately 2 feet below ground surface.

EG&G ROCKY FLATS PLANT EMD MANUAL OPERATION SOP

Manual: Procedure No.:

5-21000-OPS GT.6, Rev. 2

Page:

15D of 18 06/01/94

Category 2 Effective Date: Organization:

**Environmental Management** 

## 6.3.2.4 Inclinometer Features

A protective steel casing with hinged and locking cap and appropriate dimensions will be installed over the inclinometer casing at such a time as to maximize total productivity and minimize the possibility of damage to the casing. The protective casing will have the inclinometer designation welded on the side. The bottom of the casing will be embedded 2 to 3 feet below the ground surface in concrete. The annulus between the inclinometer casing and the protective casing will be filled with concrete to a minimum of 12 inches above the ground surface, and a 1/4-inch diameter hole will be drilled in the protective casing just above the concrete surface to allow for drainage.

At the same time the protective steel casing is concreted in place, an external concrete collar approximately 3 foot square will be placed around the protective casing at the ground surface. The collar will be graded to slope away from the casing in all directions, and will have the inclinometer designation inscribed in it before the concrete sets. If traffic or vegetation conditions warrant extra protection, four 3-inch-diameter steel posts will be installed radially from the inclinometer casing at a distance of approximately 4 feet. The posts will be filled with sand or concrete and embedded in concrete 3 feet below ground surface with a minimum of 3 feet sticking up above ground surface. If the post is filled with sand, the top 3 to 6 inches will be filled with concrete to prohibit water from entering the post.

EG&G ROCKY FLATS PLANT	Manual:	5-21000-OPS
EMD MANUAL OPERATION SOP	Procedure No.:	GT.6, Rev. 2
<del>-</del>	Page:	15E of 18
	Effective Date:	06/01/94
Category 2	Organization:	<b>Environmental Management</b>

#### 6.4 WELL POINT INSTALLATION

This Section describes the procedures used for installing well points. Before installation, sites will be located, numbered, and identified using stakes (or paint sticks on paved surfaces). Refer to SOP GT.10, Borehole Clearing, for more information regarding clearing the sites of underground obstructions.

After test sites have been located and cleared, an exclusion zone will be established according to the project Health and Safety Plan. The procedure for installing well points at a specific location is as follows:

- 1. Decontaminate the rig and downhole equipment. See SOP FO.3, General Equipment Decontamination for specific details regarding decontamination.
- 2. Set up the rig to obtain a thrust direction as close to vertical as possible.
- 3. Advance threaded expendable point by either hydraulically pushing or hammering to desired depth.
- 4. At locations within an IHSS, monitor the breathing zone near the rig for volatile organic compounds.
- 5. Insert the end of the hand-perforated tubing (Polyethylene or Teflon) with a threaded stud attached into the probe rods. Thread this into the expendable drive point. Length of perforated tubing will range between one and five feet based upon magnitude of anticipated water level fluctuations.
- 6. Hydraulically withdraw probe rods from hole.

EG&G ROCKY FLATS PLANT	Manual:	5-21000-OPS
EMD MANUAL OPERATION SOP	Procedure No.:	GT.6, Rev. 2
	Page:	16 of 18
	Effective Date:	06/01/94
Category 2	Organization:	<b>Environmental Management</b>

- 7. Place 10/20 silica sand filter pack to approximately six inches above the top of the screen while keeping tension on the tubing. Place at least six inches of granular bentonite seal above filter pack.
- 8. Install four-inch long, one-inch diameter PVC casing with threaded or slip cap as protective well-point surface casing. Protective casing will be nearly flush with the ground surface.
- 9. Install four-foot long, three-inch diameter steel post adjacent to protective casing to act as marker and traffic barrier. Post should be installed such that three feet are above ground.
- 10. Develop well point with peristaltic or inertia pump. Since these well points are only for measuring water levels, it is not necessary to measure all the parameters referenced in SOP GW.4, Well Development.
- 11. Survey top protection casing because well-point tubing is too flexible. Refer to SOP GT.17, Land Surveying, for more information regarding site surveying procedures.

### 7.0 DOCUMENTATION

Provide the WIN form to the Geosciences Division as instructed in 5.1.1. Submit copies of applicable (Sections 5.1.6 and 8.0) records related to this administrative procedure to Geosciences Division.

The installation of monitoring wells and piezometers will be documented on groundwater monitoring well and piezometer report forms. Drilling information will be documented on the Rocky Flats Plant Borehole Log form (Form GT.1A) and on the Hollow-Stem Auger Drilling form (Form GT.2A), or on the Rotary/Core Drilling form (Form GT.4A). Besides the drilling and

EG&G ROCKY FLATS PLANT	Manual:	5-21000-OPS
EMD MANUAL OPERATION SOP	Procedure No.:	GT.6, Rev. 2
	Page:	17 of 18
	Effective Date:	06/01/94
Category 2	Organization:	Environmental Management

borehole information required by these other SOPs, the following documentation will be recorded on the Groundwater Monitoring Well and Piezometer Report Form (Form GT.6A). The installation of piezometers and inclinometers will be documented on appropriate report forms. As a minimum, the following information, if applicable, will be documented on these forms. Location references will use the State Plane Coordinate System and elevations will be in feet above mean sea level (USGS datum). All depth and height measurements will be from ground surface.

- Elevation of ground surface
- Height of top of protective casing
- Height of top of well casing
- Depth of protective casing
- Type and size of protective casing
- Depth of surface seal
- Type of surface seal
- Type and size of well casing
- Type/volume of backfill
- Depth of top of seal
- Type of seal
- Depth of top of filter pack/bottom of seal
- Type/volume of filter pack
- Depth of top of screened section
- Type and size of screened section
- Size of screen openings
- Depth of bottom of screened section
- Depth of bottom of filter pack
- Length of plugged blank section (sump) below screen
- Depth of bottom of plugged blank section (sump)
- Type of backfill below filter pack

EG&G ROCKY FLATS PLANT	Manual:	5-21000-OPS
EMD MANUAL OPERATION SOP	Procedure No.:	GT.6, Rev. 2
	Page:	18 of 18
	Effective Date:	06/01/94
Category 2	Organization:	<b>Environmental Management</b>

- Diameter of borehole
- Depth of borehole
- Type and depths of centralizers if used
- Generalized stratigraphy and water level summary (based on rig geologist notes)

## 8.0 ADMINISTRATIVE DOCUMENTATION

The two forms for documenting well completion data and well installation notification for wells (and piezometers) follow the section. The Well Installation Notification Form GT.6A is completed and submitted to the Geosciences Division. Field information documented on the Groundwater Monitoring Well and Piezometer Report Form GT.6B should be entered in electronic data format as specified in SOP FO.14, Field Data Management Form FO.14G. Upon completion of data entry and quality control check, Form GT.6B is delivered to the Operable Unit Project Manager.